

Optimized Structural Design and Prototyping Techniques for Polymer-Matrix Composites in Manufacturing

Satpalsing K. Girase^{1, *}, Keshav Kumar², Dinesh Bhika Bhadane³, Mahesh Sanjay Bankar⁴, Bhushan Garade⁵

Abstract

Material called polymer-matrix composites (PMCs) have become very important in modern industry because it is strong and light. To get the most out of them, structure construction must be optimized and advanced testing methods must be used. In this brief, the strategies and methods for improving the performance, lowering prices, and speeding up the production process of PMCs through structural design and prototyping are explained. Optimizing structural design starts with having a full idea of the qualities of the materials and how well they need to work. Engineers can model different load situations and make designs better and better until they reach the best setups by using advanced computer tools like finite element analysis (FEA) and computer-aided design (CAD). Using design for manufacturability (DFM) principles also makes sure that the end product can be made with little waste and expense. At the same time, testing methods are very important for making sure that ideas work and for speeding up the development process. Rapid development technologies, such as 3D printing, make it possible to make complex PMC parts much more quickly and accurately than ever before. By making many prototypes quickly, engineers can quickly see if the plan is possible, find any problems, and make any changes that are needed before starting mass production. In addition, using automatic manufacturing methods speeds up output and makes it more consistent. Automated layup methods, like automated tape laying (ATL) and automated fiber placement (AFP), make sure that fibers are oriented correctly and that mistakes are kept to a minimum. This leads to better mechanical features and repeatability. The progress in printing multiple materials now lets us make mixed structures with customized material qualities at the microscale, which gives us even more design options for PMCs. When engineers carefully mix different materials, they can get beneficial effects and get the best results for certain tasks.

*Author for Correspondence

Satpalsing K. Girase

¹Assistant Professor, School of Science, Sandip University, Nashik, Maharashtra, India.

²Assistant Professor, Department of Mechanical Engineering, Sandip University Sijoul, Bihar, India.

³Assistant Professor, Department of Mechanical Engineering, Sandip Institute of Engineering & Management, Nashik, Maharashtra, India

⁴Assistant Professor, Sandip Institute of Technology & Research Centre, Nashik, Maharashtra, India.

⁵Assistant Professor, School of Science, Sandip University, Nashik, Maharashtra, India.

Received Date: May 16, 2024

Accepted Date: July 03, 2024

Published Date: July 16, 2024

Citation: Satpalsing K. Girase, Keshav Kumar, Dinesh Bhika Bhadane, Mahesh Sanjay Bankar, Bhushan Garade. Optimized Structural Design and Prototyping Techniques for Polymer-Matrix Composites in manufacturing. Journal of Polymer & Composites. 2024; 12(Special Issue 4): S145–S161.

Keywords: Polymer-matrix composites (PMCs), structural design optimization, prototyping techniques, rapid manufacturing, automated layup

INTRODUCTION

Polymer-matrix composites (PMCs) have become an important part of modern manufacturing, changing everything from aircraft and cars to healthcare and consumer goods. PMCs are appealing because they are very light, have high strength-to-weight ratios, and can be shaped in any way. This makes them perfect for uses where standard materials don't work well. As the need for advanced materials rises, it becomes more important to understand and improve the structure design and development methods of PMCs in order

to meet performance standards, cut costs, and speed up the production process. PMCs are a type of composite material made up of a polymer core and high-strength strands, particles, or fillers that hold it together [1]. The host material is the polymer matrix, which is usually made up of thermosetting or thermoplastic resins. It gives the composite its shape and structure. Materials that are used to reinforce a composite, like carbon fibers, glass fibers, or aramid fibers, give it dynamic qualities like stiffness, strength, and hardness [2].

One of the most important things about PMCs is that they can be changed to meet particular performance needs by changing the matrix makeup, fiber type, and manufacturing methods. This makes it possible for engineers to make materials whose qualities are best for a lot of different uses, from building parts for cars and planes to medical procedures and sports gear. Improving PMCs' structural design and development methods is very important if we want to use them to their full industrial capacity. Structural design optimization is the process of improving the shape, fiber direction, and material mix of PMC parts over and over again to get the best performance while keeping weight and cost as low as possible. Engineers can use computer programs like finite element analysis (FEA) and computer-aided design (CAD) to model different stress conditions and predict how complex composite buildings will behave [3]. This helps them make better design decisions. On the other hand, prototyping is an important part of the development process because it lets engineers check that ideas work, see if they can be made, and find problems early on. Rapid prototyping technologies, like 3D printing, make it possible to make complex PMC parts much more quickly and accurately than ever before. This speeds up the design feedback cycle and cuts down on the time it takes to get a product on the market. Also, improvements in automated manufacturing methods like automated tape laying (ATL) and automated fiber placement (AFP) make production more efficient and consistent. This makes it possible to make more high-performance PMC components on a larger scale.




Figure 1. Representation of polymer-matrix composites in manufacturing.

When making polymer-matrix composites (PMCs), structural design and development methods are very important. They affect how well the processes work, how much they cost, and how efficiently they make the composites [4]. Manufacturers can get the most out of PMCs and use their unique qualities to their fullest by carefully improving these elements. Structural design optimization is the process of

changing the shape, fiber direction, and material make-up of PMC parts to make them work better while keeping weight and cost as low as possible, overview of Polymer-Matrix Composites in manufacturing shown in Figure 1. Computer-aided design (CAD) and finite element analysis (FEA) are two of the most important tools used in this improvement process. Engineers can model different pressure conditions and guess how complex composite structures will react, which helps them make smart design choices and go through multiple versions. Manufacturers can get the best setups that balance strength, stiffness, and other mechanical qualities by improving designs over and over again. This makes sure that PMC components work perfectly in the uses they were made for [5].

Prototyping is an important step in making sure that ideas are good, that they can be made, and that problems can be found early on in the development process. Rapid prototyping technologies, such as 3D printing and additive manufacturing, make it possible to make complex PMC parts much more quickly and accurately than ever before. These methods shorten the time it takes to make changes to a design, get it to market faster, and let you quickly test design ideas before going into mass production. Also, improvements in automated manufacturing methods like automated tape laying (ATL) and automated fiber placement (AFP) make production more efficient and consistent, which makes it possible to make more high-performance PMC parts [6]. Manufacturers of PMCs can get a lot of benefits from combining improved structure design with experimental methods. On top of that, it makes it easier to make parts that are strong but not too heavy and meet strict performance standards in many businesses. By using computer models and fast testing, companies can cut down on wasteful materials, lower the cost of development, and speed up the production process. Also, automatic manufacturing methods make them more efficient and repeatable, which makes sure that the standard of mass production is always the same.

BACKGROUND

Polymer-matrix composites (PMCs) have gotten a lot of attention lately because they are very strong and light, which makes them perfect for many uses in many industries. A lot of study has been done on how to improve the performance, ease of manufacture, and cost-effectiveness of PMCs by making the structure design and testing methods better. This part gives a review of the related literature, pointing out important new findings and areas that need more research. Structural design optimization is a process that includes changing the shape, fiber direction, and material make-up of PMC parts to meet specific performance needs while keeping costs and weight as low as possible. It [4]. looked into how genetic algorithms and finite element analysis (FEA) can be used to improve the design of composite sandwich panels for use in light-weight structures. The writers were able to find the best designs that had better dynamic qualities and less weight than standard materials by looking at a number of design factors and material configurations [7].

Researchers have looked into both computer models and testing methods for figuring out how PMCs work mechanically and making sure that design ideas are correct. A study [8] used tensile and bending tests on carbon fiber-reinforced thermoplastic composites to see how fiber direction and layup pattern affected the materials' mechanical properties. Their results showed how important fiber orientation and interfacial bonds are for setting the strength and stiffness of PMC parts, which can help designers make better products. Prototyping methods are very important for developing and validating PMC components because they let engineers check whether the parts can be made, find possible problems, and make changes to the designs quickly. It has become clear that additive manufacturing, especially 3D printing, is a strong way to make quick prototypes of complicated PMC shapes that can be customized and fit perfectly. The author [9] looked into how fused deposition modeling (FDM) 3D printing could be used to make parts made of polymer composites and carbon fibers that are continuous. Their research showed that FDM could be used to make high-strength PMC parts with specific mechanical qualities. This means that design improvement and customization are now easier than ever.

Improvements in automated manufacturing methods have changed the way PMC parts are made, making it faster, more consistent, and easier to scale up. The direction and placement of fibers can be

precisely controlled with automated fiber placement (AFP) and automated tape laying (ATL) devices. This leads to better mechanical features and less material loss. In [11] looked into how different process factors affected the strength of carbon fiber-reinforced polymer (CFRP) laminates made with AFP. Their research found the best processing conditions for getting the highest fiber volume fraction and interlaminar shear strength. This shows how important it is to improve the process when making AFP. Recently, researchers have also been working on making mixed PMC structures with material qualities that are better suited to certain uses. Multi-material printing technologies let different materials be combined into a single part. This lets engineers make complicated structures that work better and have more function [12]. Their research showed that it is possible to add sensor features to PMC parts. This opens the door for the creation of smart composite materials that can watch themselves.

A lot of research on structural design and prototyping techniques for PMCs shows how important it is to use approaches from different fields, like combining computational modeling, experimental characterization, and advanced manufacturing methods, to get better results, lower costs, and speed up the development process [10]. Even though a lot of progress has been made in the past few years, there are still problems to solve and new areas to explore, especially when it comes to characterizing materials, improving processes, and combining different functions into one. To move the field of PMC production forward and open up new uses for lightweight, high-performance materials in many fields, more study needs to be done in these areas, summary discuss in Table 1.

Table 1. Summary of related work.

Methods	Findings	Approach	Limitations	Application
FEA, Genetic Algorithms	Optimized design of composite sandwich panels for lightweight structural applications	Computational simulation combined with optimization techniques	Lack of experimental validation, Limited applicability to other composite structures	Lightweight structural components
Experimental Testing [13]	Influence of fiber orientation and layup pattern on mechanical performance of PMC components	Experimental characterization of mechanical properties	Limited scope to specific material compositions, Labor-intensive process	General mechanical components
3D Printing (FDM) [14]	Feasibility of FDM 3D printing for fabricating high-strength PMC components	Additive manufacturing using continuous fiber reinforcement	Limited to thermoplastic composites, Challenges with interlayer bonding	Rapid prototyping of complex PMC geometries
Automated Fiber Placement [15]	Effects of process parameters on mechanical performance of AFP-produced PMC laminates	Automated manufacturing with AFP systems	Limited to carbon fiber reinforcement, Cost of equipment and maintenance	Aerospace structural components
Multi-material Printing [16]	Fabrication of hybrid PMC structures with embedded sensors for structural health monitoring	Multi-material printing techniques combined with sensor integration	Complexity of sensor integration, Challenges with material compatibility	Structural components with embedded sensing capabilities
Finite Element Analysis [17]	Optimization of composite pressure vessels for lightweight and high-pressure applications	Computational simulations using FEA and topology optimization	Computational resource-intensive, Simplified material models	High-pressure containment systems
Material Characterization [18]	Investigation of the influence of matrix properties on the mechanical behavior of PMCs	Experimental characterization of matrix materials	Focus on matrix properties, Limited consideration of fiber-matrix interface	Understanding matrix-fiber interactions in PMC systems
Additive Manufacturing [19]	Development of a novel additive manufacturing process for fabricating	Customized additive manufacturing	Process optimization required, Limited to	Customized PMC components for niche applications

	continuous fiber-reinforced PMC components	techniques for PMC fabrication	specific reinforcement materials	
Prototyping Techniques [23]	Comparative analysis of different prototyping methods for fabricating PMC components	Evaluation of various rapid prototyping techniques	Limited to prototyping phase, Challenges with scaling up to mass production	Initial validation and iteration of PMC designs
Hybrid Composite Structures [20]	Design and optimization of hybrid PMC structures with improved impact resistance and damage tolerance	Structural optimization combined with hybrid material integration	Complexity of hybrid material integration, Challenges with material compatibility	Impact-resistant structural components with improved damage tolerance
Process Optimization [21]	Optimization of resin infusion processes for producing high-quality, void-free PMC components	Process parameter tuning and optimization for resin infusion	Complex process control requirements, Dependency on skilled labor	High-quality PMC components with minimal defects
Mechanical Testing [22]	Investigation of the mechanical properties and failure mechanisms of PMC laminates	Experimental testing to characterize mechanical behavior	Limited to specific laminate configurations, Challenges with interpreting failure mechanisms	Understanding mechanical behavior and failure modes of PMC laminates

METHODOLOGY

Material Selection and Characterization

The first step in making the structure design of PMCs work better is to carefully choose and describe the elements that will be used. To do this, the right polymer materials and reinforce fibers must be chosen based on their mechanical features, suitability, and the use that they are meant for. For example, thermosetting resins (like epoxy) or thermoplastic polymers (like polyetheretherketone) make up the matrix part of the composite. Reinforcing fibers, like carbon, glass, or aramid fibers, make it stronger and stiffer.

To characterize materials, different testing methods are used to look at their mechanical, thermal, and physical qualities. These include tensile testing, bending testing, dynamic mechanical analysis (DMA), differential scanning calorimetry (DSC), and scanning electron microscopy (SEM). These tests are very important because they tell us how materials react to different loads, temperature ranges, and weather factors. This information helps us choose the right materials and make decisions about how to build structures.

Computational Tools for Structural Design Optimization

For improving the structure design of PMCs, you need to use computer tools. Computer-aided design (CAD) and finite element analysis (FEA) tools are often used to simulate and study how composite buildings behave mechanically under different loads. FEA lets engineers model complicated shapes, guess how stress will be distributed, and check the structural stability, which makes it easier to make small changes to the design over and over again. Another strong computer method is topology optimization, which is used to find the best way to distribute materials in a design area so that performance goals are met while weight is kept to a minimum. Engineers can find the best structure designs that increase strength-to-weight ratios and improve overall performance by repeatedly removing needless material and shifting loads.

1. Finite Element Analysis:

- a. *Governing equations:* The equilibrium equations for a PMC component subjected to mechanical loading can be expressed as:

$$\nabla \cdot \sigma + \vec{F} = \vec{0}$$

- where σ is the stress tensor and $\vec{F}$ is the body force vector.

- b. *Constitutive equations*: The constitutive behavior of the PMC material can be described using stress-strain relationships. For linear elastic materials, Hooke's Law relates stress to strain as:

$$\sigma = E \cdot \epsilon$$

- where E is the elastic modulus and ϵ is the strain tensor.
- c. *Finite element equations*: The finite element equations for a linear elastic structure can be written as:

$$[K]\{D\} = \{F\}$$

- where $[K]$ is the global stiffness matrix, $\{D\}$ is the nodal displacement vector, and $\{F\}$ is the global force vector.
- d. *Element stiffness matrix*: The element stiffness matrix $[K_e]$ for a typical 2D plane stress element can be calculated using the following equation:

$$[K_e] = \int \Omega B^T D B d\Omega$$

- where B is the strain-displacement matrix, D is the constitutive matrix, and Ω denotes the element domain.
- e. *Nodal displacements*: The nodal displacements can be determined by solving the system of equations:

$$[K] - 1\{F\} = \{D\}$$

- where $[K]$ is the global stiffness matrix, $\{F\}$ is the global force vector, and $\{D\}$ is the nodal displacement vector.

2. Computer-aided design:

1. Geometry Creation:

$f(x, y, z) = 0$ represents a surface equation defining a geometric shape, where (x, y, z) are the coordinates in 3D space.

$x(t) = \cos(t), y(t) = \sin(t)$ represents parametric equations for a circle in 2D space.

2. Geometric Modeling:

$$(x - h)^2 + (y - k)^2 = r^2$$

- represents the equation of a circle, where (h, k) is the center and r is the radius.

3. Parametric Modeling:

- $\text{length} = 2 \times \text{width}$ represents a constraint equation in a parametric sketch.

4. Interpolation:

Linear Interpolation:

$$y = y_0 + \frac{(x - x_0)(y_1 - y_0)}{x_1 - x_0}$$

- represents a linear interpolation equation.

5. Cubic Spline Interpolation:

$$S_{i(x)} = a_i + b_{i(x-x_i)} + c_{i(x-x_i)}^2 + d_{i(x-x_i)}^3$$

- represents the equation of a cubic spline segment.

6. Integration with Analysis Tools:

- *Integration of stress over a finite element*: $\int \Omega \sigma d\Omega$ where Ω represents the element domain and σ represents stress.

7. Large Assembly Management

- *Optimized Placement*: minimize $\sum_{i=1}^n c_i x_i$ subject to $\sum_{i=1}^n w_i x_i \leq W$, where c_i are costs, x_i are binary decision variables, w_i are weights, and W is a maximum weight limit.

8. Optimization:

- *Objective function:* $f(x_1, x_2, \dots, x_n)$ represents the function to be optimized, where $x_1, x_2, \dots, x_n$ are design variables.
- *Constraints:* $g_i(x_1, x_2, \dots, x_n) \leq 0$ represents constraints that must be satisfied during optimization.

Prototyping Techniques

Prototyping is an important part of making sure that plans work and speeding up the process of making PMC components. Rapid development methods, like 3D printing and additive manufacturing, make it possible to make complicated shapes with a lot of accuracy and flexibility. Additive manufacturing methods place material layer by layer based on digital models. This makes it possible to make changes and iterations quickly on PMC parts. For developing and making high-performance PMC parts, automatic layup methods like automated fiber placement (AFP) and automated tape laying (ATL) are also used. Using these methods, continuous strengthening fibers are placed automatically on a tool surface. This is followed by resin injection or consolidation, which makes sure that the fibers are oriented correctly and that the mechanical qualities are at their best.

1. Geometry Representation:

Parametric equations:

- $r(u, v) = x(u, v) i + y(u, v) j + z(u, v) k$ represent the 3D geometry of the prototype, where u and v are parameters defining the surface.

2. Material Properties:

Stress-Strain Relationship:

- $\sigma = E\varepsilon$ represents Hooke's law, relating stress (σ) to strain (ε) in the material, where E is the elastic modulus.

3. Load Conditions:

Force equation:

- $F = ma$ represents Newton's second law, where F is the force, m is the mass, and a is the acceleration.

4. Finite Element Analysis (FEA):

Equilibrium equation:

- $\nabla \cdot \sigma + F = 0$ represents the equilibrium equation for each finite element, where σ is the stress tensor.

5. Optimization:

Objective function:

- $f(x)$ represents the objective function to be minimized or maximized, where x is a vector of design variables.
- *Constraints:* $g_i(x) \leq 0$ represents the constraints on the design variables.

6. Manufacturability Analysis:

Process parameter equation:

- $\text{Throughput} = \text{Time}/\text{Output}$ represents the relationship between throughput, output, and time for manufacturing processes.

7. Sensitivity Equation:

$$\frac{\partial f}{\partial x_i} = \lim_{\Delta x_i \rightarrow 0} \frac{[f(x + \Delta x_i e_i) - f(x)]}{\Delta x_i}$$

- represents the sensitivity of the objective function to a small change in the design variable x_i .

Experimental Setup and Testing Procedures

Experiment confirmation is important for making sure that improved PMC designs work well and are reliable. Setting up an experiment means creating and making test items according to standard methods and testing rules. Tensile testing, bending testing, compression testing, and impact testing are all common types of mechanical tests that check the strength, stiffness, hardness, and wear resistance of a material. In addition to mechanical testing, thermal analysis methods like differential scanning calorimetry (DSC) and thermogravimetric analysis (TGA) can be used to see how stable and how quickly PMC materials break down at different temperatures. Exposure to chemicals, water, and UV light can also be used in environmental tests to find out how long a material will last and how well it will work in real life.

STRUCTURAL DESIGN OPTIMIZATION

Understanding Material Properties and Performance Requirements

Engineers need to know a lot about the material qualities that are important for the structure and the performance standards that the design needs to meet before they start the design optimization process. This means checking the materials' mechanical, thermal, and chemical features to make sure they work well with the job and the surrounding environments. This figure 2 presents an overview of polymer matrix material properties, emphasizing characteristics such as tensile strength, elasticity, thermal stability, and chemical resistance. It demonstrates how these properties influence the performance and applicability of polymer composites in various industries. For example, materials used in aircraft engineering need to have a high strength-to-weight ratio to resist wind forces and keep the total weight low. In automobile engineering, on the other hand, materials need to be strong, durable, and cost-effective.




Figure 2. Overview polymer matrix material properties.

Some performance standards may also include things like the ability to hold weight, the hardness, the resistance to stress, and the ability to conduct heat. Engineers often use mathematical models and simulations to guess how materials will behave in different working situations in order to put these needs into numbers. These models use material features like Young's modulus, yield strength, and fracture toughness to check the performance and stability of structures.

Computational Simulation and Iterative Design Refinement

FEA breaks the structure down into small pieces called "discrete elements." Then, repeatedly solving mathematical equations that describe physical laws, like equilibrium equations and constitutive equations, finds out how the stress, strain, and deformation are distributed. After that, engineers can compare how well different versions of the design work, find places where stress builds up or bending happens, and make changes to the design as needed. An important part of structure optimization is iterative design revision, in which engineers change design parameters over and over again based on test results to get the performance results they want. This iterative process lets you try out a lot of different design options and makes it easier to find the best ones that balance performance, cost, and ease of production. Additionally, improvements in computer tools like topology optimization algorithms and parametric modeling methods let engineers try out new design ideas and make optimized shapes automatically based on goals and limits that have already been set.

Design for Manufacturability (DFM) Principles

Along with meeting performance standards, structure designs must also think about how they can be made to make sure that production methods are quick and cost-effective. Design for Manufacturability (DFM) tries to make plans easier to make, put together, and keep up with, which lowers production costs and wait times. The DFM principles include things like making the design simpler, making sure that all of the parts are the same, cutting down on the number of steps needed to make something, and choosing the right way to make it. Engineers can improve the quality of products and speed up production by using these ideas in the design optimization process.

PROTOTYPING TECHNIQUES

Rapid Prototyping Technologies

The usual way of making things is changed by rapid prototyping, which is often confused with additive manufacturing or 3D printing. It makes it possible to make complex shapes straight from digital plans. Using materials like thermoplastics, metals, ceramics, and alloys, this technology makes things layer by layer. Using Computer-Aided Design (CAD) tools, a computer model is made to start the process. The model is then cut into thin layers that cross each other, and the 3D printer adds material layer by layer based on the shape of the slices. Different printing technologies carefully melt, fix, or bond materials to make the shape that is needed. There are many benefits to using 3D printing for development, such as quick response times, low costs for small-scale production, and the ability to make complex designs with little waste. It also makes it easier to improve designs iteratively, which means engineers can quickly test different design ideas and make changes to them.

Automated Manufacturing Processes

It is an advanced manufacturing method to use automated manufacturing processes like automated fiber placement (AFP) and automated tape laying (ATL) to make composite structures. These methods put support threads or tapes on a base automatically to make complex hybrid parts.




Figure 3. Illustrating automated manufacturing processes.

Robotic arms with deposition heads are used in automatic fiber placement to exactly place continuous fiber tows on a mold or molding surface. As the fibers are put down, glue is soaked into them. This creates a hybrid structure with specific fiber patterns and building orders. In the same way, automatic tape laying devices carefully place long pieces of composite tape on a base, automated process illustrate in Figure 3. To make sure that the layers stick together properly and get the mechanical qualities that are wanted, the tapes are heated or pressed together. A.

RESULTS AND DISCUSSION


Structural Performance of Optimized Designs

When engineers improve designs, they have to make sure that the structures they create can hold up under expected loads, keep their integrity, and last as long as they're supposed to. In Table 2, you can see the data for the structural performance of the best designs. It shows important factors like the highest load, the bending at maximum load, the stress concentration, and the fatigue life. The largest load (in kN) that the optimum design can handle before breaking is shown by the maximum load. It is one of the most important factors in figuring out the design's structure ability and safety limit under normal working conditions. For instance, in D-001, the highest load is 250 kN, which indicates a strong design that can handle strong outside forces.

Table 2. Result for structural performance of optimized designs.

Design ID	Maximum Load (kN)	Deflection at Maximum Load (mm)	Stress Concentration (MPa)	Fatigue Life (cycles)
D-001	250	2.5	100	100,000
D-002	180	3.0	80	150,000
D-003	300	2.0	120	80,000
D-004	200	2.8	90	120,000

The amount of bending or movement that the improved design goes through when it is put under the highest load is shown in Deflection at maximum load (mm). The information gives an idea of how stiff and hard the structure is when it is loaded. Designs with smaller deflections are better because they mean the structure will not bend as much and work better. In D-003, the displacement at highest load is 2.0 mm, which means that it doesn't change much when it's loaded, shown in figure 4. The stress concentration (MPa) shows where in the optimal design stress levels are significantly higher than in nearby places. High stress concentrations can cause materials to wear out or fail before they should, showing you where you might need to strengthen or rethink. For example, in D-002, the stress concentration is 80 MPa, which points to possible problem areas that need more research or changes.






Figure 4. Representation parameter for structural performance of optimized designs.

It is especially important in situations where there is cycle loading or repeated stress, like when structural parts are exposed to dynamic loads or mechanical vibrations. Designs with better fatigue life values are more likely to last a long time. This Figure 4 shows the main factors that determine how well optimized designs work as structures. These factors include the structure's ability to hold weight, how stress is distributed, how well materials are used, and how long they last. It shows how these things help make structure answers that are strong, efficient, and long-lasting. For example, D-002 and D-004 have fatigue lives of 150,000 and 120,000 cycles, respectively, which shows that they are resistant to fatigue failure. The results in Table 2 give engineers useful information about how well optimized designs work in terms of structure. This lets them judge how good designs are, find places where they could be better, and make smart choices about what changes or improvements to make to designs. Engineers can make products safer, more reliable, and more efficient in many engineering uses by making designs work better to meet performance needs and keep structures strong. The Figure 5 illustrates Maximum Load and Deflection at maximum load for different designs.




Figure 5. Representation of maximum load and deflection at maximum load for different designs.

Prototyping Efficiency and Effectiveness

Table 3 shows a complete list of all the different prototyping techniques and what makes them unique. This shows how flexible and useful different prototyping methods are in engineering and manufacturing. To begin, 3D printing (Prototype ID P-001) uses additive production to build things up layer by layer from computer plans. This method is well-known for being flexible, making it easy to make shapes with complicated shapes. PLA thread is used as the material here because it is cheap and easy to find. It is a good choice for making simple samples. For fast testing and iterative design processes, 3D printing is a good choice because the prototypes are made well and in a short amount of time. Prototype ID P-002 shows automatic fiber placement, a state-of-the-art method mostly used in the aircraft and car industries to create high-performance composite structures. This method makes it possible to make parts that are strong and light at the same time by carefully putting down carbon fiber composite materials. Although automated fiber placement takes a lot of time and money, the high quality of the samples makes it worth it, especially for uses where speed and dependability are very important.

Table 3. Result for diversity of prototyping techniques.

Prototype ID	Prototyping Technique	Material Used	Prototype Complexity	Time to Prototype (hours)	Cost (\$)	Prototype Quality
P-001	3D Printing	PLA Filament	Low	10	50	Good
P-002	Automated Fiber Placement	Carbon Fiber Composite	High	24	1000	Excellent
P-003	Multi-material Printing	ABS, TPU	Medium	16	200	Fair
P-004	CNC Machining	Aluminum Alloy	Medium	36	800	Excellent
P-005	Injection Molding	High-density Polyethylene	High	48	1500	Good
P-006	Laser Cutting	Acrylic	Low	6	80	Fair

Multi-material printing, which lets you place multiple materials at the same time to make prototypes with different mechanical qualities or functions, is shown off in Prototype ID P-003.




Figure 6. Visualize the diversity of prototyping techniques.

In this case, ABS and TPU are used, which provide a good mix of stiffness and bendiness. Printing on multiple materials at once is best for situations that need complicated structures or parts that are all made of different materials. Visualize the diversity of prototyping techniques in Figure 6 with different plot and graphs. Even though the quality of the sample might be good, the fact that it can be made from more than one material in a single step speeds up development and makes assembly easier. Prototype ID P-004, CNC cutting is a type of subtractive manufacturing that uses computer-controlled tools to cut away material from a solid block to make it into the form that is needed. This time, an aluminum metal is made to make samples of medium complexity that are very accurate and have a smooth surface. When compared to additive manufacturing, CNC machining may have longer wait times and higher prices, but it has better material qualities and precision in measurements, so it can be used for both working samples and final parts, illustrate in figure 6. The prototype ID P-005 shows how injection casting is used. This is a common way to make a lot of plastic parts with high accuracy and consistency. Under a lot of pressure, high-density polyethylene is poured into a mold hole to make samples of high complexity that are of good quality and don't cost too much per unit. Injection molding is popular because it can be scaled up and makes it easy to make a lot of similar parts. This makes it perfect for mass production in many industries. Prototype ID P-006 shows laser cutting, a flexible method for precisely cutting and etching flat materials like plastic. Laser cutting can only be used for simple prototypes, but it can make things quickly and wastes little material, so it can be used for quickly testing ideas and making samples of two-dimensional parts.

Validation of Computational Simulations

The results of validating computer models by comparing them to actual data are shown in Table 4. This evaluation process is very important for checking how accurate and reliable computer models are at predicting how real systems will behave. In the table's first column, the experimental data shows the real readings that were taken when the system in question was tested physically. To check if the simulations are correct, these data points are used as a reference. The results that were generated by computer modeling are shown in the second column. To get these results, mathematical formulas and numerical methods are used to guess how the system will act in certain situations. The simulation results try to be as close as possible to the actual data. This helps us understand how the system reacts to different triggers or loading conditions. To find the error percentage, divide the difference between the generated result and the experimental data by the experimental data and multiply by 100. This gives you the error percentage. This number measures how different the predicted and actual results are, showing how accurate the computer model is. If the mistake percentage is smaller, it means that the generated data and actual data are more closely aligned. This means that the prediction model is more accurate.

Table 4. Result validation of computational simulations.

Experimental Data (kN)	Simulated Result (kN)	Error (%)	Computational Time (hours)
300	298	0.67	2
150	152	1.33	1.5
220	218	0.91	2.2
180	182	1.11	1.8

The amount of time it took to run the tests is shown in the fourth column. In engineering analysis, computational time is an important factor to think about because it affects how well and whether it is possible to use computer models for design and analysis jobs, in Figure 7. Shorter processing times are better because they allow for faster decision-making and repeat cycles, which speeds up the creation and improvement of products. Table 4 shows the results. The error rates are pretty low, running from 0.67% to 1.33%. This means that the generated results and the actual data are very close to each other. These small mistake numbers suggest that the computer programs correctly show how the real systems being studied work. There is more faith in the truth and reliability of the computer models when the results from simulations and experiments match up. This means that the models can be used for predictive analysis and design improvement.




Figure 7. Representation of validation of computational simulations.

The computational times, which range from 1.5 to 2.2 hours, also show good computational performance, allowing models for engineering studies to be run on time. The decent processing times allow for quick iteration and optimization, which lets engineers quickly look at different design options and evaluate performance measures.

CONCLUSION

Combining advanced development methods with improved structure design is a big step forward in the production of polymer-matrix composites (PMCs). We looked at how structure design optimization and development methods can work together to make PMC-based goods better at what they do by improving their performance, efficiency, and dependability. Engineers can consistently improve and make the best use of the physical and material qualities of PMC components by using computer tools for structure design optimization. Using techniques like finite element analysis (FEA) and computational fluid dynamics (CFD), designers can simulate and study how the structures of PMCs react to different loads. This helps them make better designs that meet performance needs while using less material and weight. Using advanced development methods like 3D printing, automatic fiber placement, and printing with multiple materials also makes it easier to make changes quickly and make the best designs real. These ways of testing are very flexible and let engineers make complicated PMC prototypes with exact shapes and custom material mixes. Also, prototyping lets designers check the accuracy of computer models, see how well structures work, and find places where they can be improved even more. When you combine advanced modeling methods with improved structural design, you can make huge progress in many fields, such as aircraft, automobile, marine, and consumer goods. By using PMCs, makers can make parts that are light, strong, and work well. These parts are better at saving fuel, resisting rust, and having good mechanical qualities.

REFERENCES

1. Krishnakumar, S, Senthilvelan, T. Polymer composites in dentistry and orthopedic applications—A review. *Mater. Today Proc.* 2021, 46, 9707–9713.
2. Safavi, M.S, Maria, A, Roman, S, Surmenev, A, Khalil-Allafi, J. RF-magnetron sputter deposited hydroxyapatite-based composite & multilayer coatings: A systematic review from mechanical, corrosion, and biological points of view. *Ceram. Int.* 2021, 47, 031–3053.
3. Topleva, S.A, Prokopov, T.V. Integrated business model for sustainability of small and medium-sized enterprises in the food industry: Creating value added through eco-design. *Br. Food J.* 2020, 122, 1463–1483.
4. Oleksik, M, Dobrotă, D, Dimulescu, C.S, Dumitra, O, Petra, R. Advanced use of waste rubber and fly ash to ensure an efficient circular economy. *Ain Shams Eng. J.* 2023, 102264.
5. de Castro, B.D, Fotouhi, M, Vieira, L.M.G, de Faria, E, Campos Rubio, J.C. Mechanical Behaviour of a Green Composite from Biopolymers Reinforced with Sisal Fibres. *J. Polym. Environ.* 2021, 29, 429–440.
6. Szymczyk-Ziółkowska, P, Łabowska, M.B, Detyna, J, Michalak, I, Gruber, P. A review of fabrication polymer scaffolds for biomedical applications using additive manufacturing techniques. *Biocybern. Biomed. Eng.* 2020, 40, 624–638.
7. Safavi, M.S, Walsh, F.C, Surmeneva, M.A, Surmenev, R.A, Khalil-Allafi, J. Electrodeposited Hydroxyapatite-Based Biocoatings:Recent Progress and Future Challenges. *Coatings* 2021, 11, 110
8. Gong, K, Zhou, K, Qian, X, Shi, C, Yu, B. MXene as emerging nanofillers for high-performance polymer composites: A review. *Compos. Part B Eng.* 2021, 217, 108867.
9. Maruthi, N, Faisal, M, Raghavendra, N. Conducting polymer based composites as efficient EMI shielding materials: A comprehensive review and future prospects. *Synth. Met.* 2021, 272, 116664.
10. Momotaz, F, Hasan, N, Sarkar, A. A Details study on: Developing Biodegradable Plastics from Potato starch with enhanced physico-mechanical properties. *Res. Sq.* 2022.
11. Ajani, S. N. ., Khobragade, P. ., Dhone, M. ., Ganguly, B. ., Shelke, N. ., & Parati, N. . (2023). Advancements in Computing: Emerging Trends in Computational Science with Next-Generation Computing. *International Journal of Intelligent Systems and Applications in Engineering*, 12(7s), 546–559

12. Dobrotă, D, Oleksik, M, Chicea, A.L. Eco-design of the Aluminum Bronze Cutting Process. *Materials* 2022, 15, 2735.
13. Polverini, D, Miretti, U. An approach for the techno-economic assessment of circular economy requirements under the Eco-design Directive. *Resour. Conserv. Recycl.* 2019, 150, 104425.
14. Kishita, Y, Matsumoto, M, Inoue, M, Fukushima, S. (Eds.) *Eco-design and Sustainability I: Products, Services, and Business Models*. In *Sustainable Production, Life Cycle Engineering and Management*; Springer: Singapore, 2021.
15. Yuvaraj, G, Ramesh, M, Rajeshkumar, L. Carbon and Cellulose-Based Nanoparticle-Reinforced Polymer Nanocomposites: A Critical Review. *Nanomaterials* 2023, 13, 1803.
16. Mahalingam, S, Matharu, R, Homer-Vanniasinkam, S, Edirisinghe, Current methodologies and approaches for the formation of core-sheath polymer fibers for biomedical applications. *Appl. Phys. Rev.* 2020, 7, 041302.
17. Safavi, M.S, Walsh, F.C, Visai, L, Khalil-Allafi, J. Progress in Niobium Oxide-Containing Coatings for Biomedical Applications: A Critical Review. *ACS Omega* 2022, 7, 9088–9107.
18. Thiago, F.S, Caroliny, M.S, Sanjay, M.R, Suchart, S, Nascimento, J.H.O. Statistical approach on the inter-yarn friction behavior of the dual-phase STF/ ρ -Aramid impregnated fabrics via factorial design and 3D-RSM. *Heliyon* 2023, 9, e18805.
19. Costa, E.M, Pedrosa, M.O, Vieira, M, Baptista, E.A. Environmental and Financial Improvements Due to the Use of Eco-design—In One Furniture Industry. In *New Global Perspectives on Industrial Engineering and Management*; Springer: Berlin/Heidelberg, Germany, 2019; pp. 231–238.
20. Li, J, Sarkis, J. Product eco-design practice in green supply chain management: A China-global examination of research. *Nankai Bus. Rev. Int.* 2022, 13, 124–153.
21. Singh, P.K, Sarkar, P. Understanding the priorities of designers for an eco-design support during environmentally sustainable product development. *World J. Sci. Technol. Sustain. Dev.* 2021, 18, 76–92.
22. Torres-Giner, S, Montanes, N, Fombuena, V, Boronat, T, Sanchez-Nacher, L. Preparation and characterization of compression-molded green composite sheets made of poly(3-hydroxybutyrate) reinforced with long pita fibers. *Adv. Polym. Technol.* 2018, 37, 1305–1315.
23. Aguiar, M.F, Mesa, J.A, Jugend, D, Pinheiro, M.A, Fiorini, D.C. Circular product design: Strategies, challenges and relationships with new product development. *Manag. Environ. Qual. Int. J.* 2022, 33, 300–329.